

B7 HEAVY HEX BOLTS TO ASTM A193 PLAIN FINISH										
									PAGE 2 OF 4	
Thread →	1/2-13	5/8-11	3/4-10	7/8-9	1-8	1 1/8-7	1 1/4-7	1 1/2-6	1 3/4-5	2-4 1/2
Length ↓	UNC	UNC	UNC	UNC	UNC	UNC	UNC	UNC	UNC	UNC
7 1/4										
7 1/2		X			X	X	X	X	X	
7 3/4										
8		X	X	X	X	X	X	X	X	X
8 1/4										
8 1/2					X	X	X	X		
8 3/4										
9				X	X	X	X	X	X	X
9 1/2						X	X	X	X	
10						X	X	X	X	X
10 1/2						X	X	X		
Thread →	1/2-13	5/8-11	3/4-10	7/8-9	1-8	1 1/8-7	1 1/4-7	1 1/2-6	1 3/4-5	2-4 1/2
Length ↓	UNC	UNC	UNC	UNC	UNC	UNC	UNC	UNC	UNC	UNC
11						X	X	X		
11 1/2						X	X	X		
12						X	X	X	X	X
13								X	X	
14										X
SCROLL DOWN FOR 8TPI										

8TPI HEAVY HEX BOLTS TO ASTM A193 PLAIN FINISH								PAGE 3 OF 4
Thread →	1 1/8-8	1 1/4-8	1 3/8-8	1 1/2-8	1 5/8-8	1 3/4-8	2-8	
Length ↓	8TPI	8TPI	8TPI	8TPI	8TPI	8TPI	8TPI	
3	X							
3 1/4	X							
3 1/2	X							
3 3/4	X							
4	X	X		X		X		
4 1/4								
4 1/2	X	X		X				
4 3/4	X	X						
5	X	X		X		X		
5 1/4								
5 1/2		X		X		X		
5 3/4								
Thread →	1 1/8-8	1 1/4-8	1 3/8-8	1 1/2-8	1 5/8-8	1 3/4-8	2-8	
Length ↓	8TPI	8TPI	8TPI	8TPI	8TPI	8TPI	8TPI	
6	X	X		X		X		
6 1/4								
6 1/2	X	X		X				
SCROLL DOWN FOR LONGER LENGTHS B7 8TPI								

8TPI HEAVY HEX BOLTS TO ASTM A193 PLAIN FINISH								PAGE 4 OF 4
Thread →	1 1/8-8	1 1/4-8		1 1/2-8	1 5/8-8	1 3/4-8	2-8	
Length ↓	8TPI	8TPI		8TPI	8TPI	8TPI	8TPI	
7	X	X		X		X		
7 1/4								
7 1/2	X	X		X		X		
7 3/4								
8	X	X		X		X	X	
8 1/4								
8 1/2	X	X		X		X		
8 3/4								
9	X	X		X		X	X	
9 1/2	X	X		X		X		
10	X	X		X		X	X	
10 1/2	X	X		X				
11	X	X		X		X		
11 1/2	X	X	X	X				
12	X	X		X	X	X	X	
13								
14				X				